



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 05/10/2016

Reviewed

[Signature]

Mine Name: Leamington Cement Plant	Permit Number: M/023/0004	Mine Status: Active
Operator Name: Ash Grove Cement	Inspection Date: 04/28/2016	Permit Fees:
Inspector(s): Wayne Western	Inspection Time: 11:30 am -12:50 pm	Bond Amount: \$6,857,000
Attendee(s): Gordon Jarrett	Weather:	Bond Escalation: 07/22/2017
Inspection Purpose: Routine inspection		Prior Inspection: 04/07/2015

Conclusions and Recommendations

Camera was not working.

Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds Permits and bond are current.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls) Mine is adjacent to public highway. Access to the site is controlled. There are no underground opening except blast holes. Highwalls exist on site.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages/Erosion Control No issues with drainage or erosion control.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material Site is well kept and no problem with deleterious materials.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature:

[Signature]

CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M023-Juab/M0230004-Leamington/Inspections/Insp04232016.pdf

